



www.idealindustries.com

Updates

- **July 26, 2006** – Added reference to newer (LANTEK 6A and 7G) models. New software version 2.508 required for all LANTEK units. Updated p/n for optional Siemon patch cord.
- **May 30, 2007** – New software version 2.600 required for LT 8100, 8155 and 8600 units.
- **May 30, 2007** – New software version 2.510 required for all LANTEK units.
- **May 30, 2007** – Added Premium 6[®] to system options.

SYSTEM 5e[®], PREMIUM 5e[®]

Tester Model	Software Version	Link Adapter	Channel Adapter
LT 8100	2.600	LT8BASIC	LT8CHANNEL
LT 8155	2.600	LT8BASIC	LT8CHANNEL
LT 8600	2.600	LT8BASIC	LT8CHANNEL
LANTEK 6 LANTEK 6A LANTEK 7 LANTEK 7G	2.510	0012-00-0629 with IDEAL 6011-50-0029' patch cord	0012-00-0629

Notes:

SYSTEM 6[®], PREMIUM 6[®]

Tester Model	Software Version	Link Adapter	S210 Adapter (T568A)	S210 Adapter (T568B)	Channel Adapter
LT 8600	2.600	B6SIEMON001	NA	NA	NA
LANTEK 6 LANTEK 6A LANTEK 7 LANTEK 7G	2.510	0012-00-0629 with IDEAL 6011-50-0029 ¹ patch cord	NA	NA	0012-00-0629

Notes:

NA = Not available/approved at this time.

¹ The Siemon 10GMCS-07-B(XX) Patch Cord can also be used.